

# **Model of water leakage beneath reservoir and above diversion water tunnel; Mae Prachum reservoir area, Mae Taeng District, Chiang Mai Province**

<sup>1st</sup>Noppadol Poomvises, Anchalee Kongsuk,  
Benjamas Sawasdipong, and Tanapon Suklim

**Bureau of Engineering Topographical and Geotechnical Survey  
Royal Irrigation Department, Samsen rd., Bangkok, Thailand**

- Drought : Mae Kuang
- 2015
- Water-rich → Water-lack
- Diversion tunnel
  - 47 km, convey 160 MCU of water
  - Mae Taeng – Ma Ngad – Mae Kuang reservoir




# 2018 - 2019

- Construction beneath a small-scale reservoir, Huai Mae Prachum, Mae Taeng, Chiang Mai
- Storage water level in the reservoir rapidly drew down
- Srisuthum, C. and team 2020, walk-thru survey
- A large amount of water in reservoir flew into the tunnel conduit, in the meantime of construction.
- Detail geophysical and geological survey for improvement
- 2021 Run geophysics

# GEOLOGIC MAP

★ Huai Mae Prachum


Faults




Cr. Singdaeng (2015)



# GEOLOGICAL MAP



## Geological profile along main tunnel from Mae Ngad to Mae Kuang reservoir





# Thrust fault, downstream area of Mae Prachum






Mae Ngad  
reservoir

# Geological prediction of main tunnel

Mae Kuang  
reservoir






# Geological prediction of foundation of Mae Prachum reservoir

Mae Ngad

Mae Kuang



C

CP

C

Low-angle Thrust fault

Fracture / Fault / Sheared zone

Fracture / Fault / Sheared zone / Rock unit


**Mae Prachum**


# Seismic reflection profile along tunnel and touch two reservoir rims


Mae Ngad

Mae Kuang

Looking upstream









295.00 m

DHW-6 (+499.987)




DHW-8 (+415.056)




สัญลักษณ์ดินและหิน

- Legend for soil and rock symbols: ดินเหนียว (CLAY), ทรายแป้ง (SILT), ทราย (SAND), กรวด (GRAVEL), หินทราย (SANDSTONE), หินทรายแป้ง (SILTSTONE), หินโคลน (MUDSTONE), หินดินดาน (SHALE), หินปูน (LIMESTONE), หินเชิร์ต (CHERT), หินถูกแรงเฉือนกระทำ (SHEARED MATERIAL), หงรอยเลื่อน (GOUGE) และกรวดรอยเลื่อน (BRECCIA), เศษหินจากการเจาะ (CUTTING)


DHW-4 (+393.533)



DHW-7 (+447.661)



DHW-9 (+431.868)




อัตราการผลิตพลังงาน

- FR = หินผล
SW = หินผลลายตัวน้อย
MW = หินผลลายตัวปานกลาง
HW = หินผลลายตัวสูง
CW = หินผลลายตัวสมบูรณ์

กรมชลประทาน
โครงการอุโมงค์คลองน้ำแม่จืด-แม่กวัง
จังหวัดเชียงใหม่
การสำรวจทางธรณีวิทยาฐานราก
รายละเอียดข้อมูลหลุมเจาะธรณีวิทยาฐานราก (แผ่นที่ 1/3)



# Geophysics ; 2-D electrical resistivity survey





# Ground survey, RTK-GNSS, in rainy days





# Resistivity in cloudy days







Google Earth Pro

ไฟล์ แก้ไข มุมมอง เครื่องมือ เพิ่ม ความช่วยเหลือ

ค้นหา

อ่างเก็บน้ำห้วยแม่ประจุม ค้นหา

ตัวอย่าง: พืชป่าใกล้สวนสาธารณะ  
รับเส้นทาง ประวัติ


อ่างเก็บน้ำห้วยแม่ประจุม

สถานที่

- ☒ สถานที่ของจีน
- ☒ **ทัวร์ชมสถานที่**  
โปรดตรวจสอบว่าได้ทำ  
3 มิตินแล้ว
- ☐ สถานที่ชั่วคราว

เลเยอร์

- ☒ ฐานข้อมูลหลัก
- ☐ ประกาศ
- ☒ กรอบและป้ายชื่อ
- ☒ สถานที่
- ☐ ภาพถ่าย




# Survey lines (yellow) and tunnel route red



Google Earth

วันที่เก็บภาพ: 1/21/2019 19°06'41.05"น. 99°05'12.37"ตอ. ความสูง 461 ม. ความสูงระดับสายตา 1.18 กม.





# Resistivity survey





# Walk-thru survey

Fracture (white dot)

Opened fracture  
(white ellipse)








Fig.1. Rock exposures at Huai-Khun-Mi, showing opened joint, fracture, and cavity (white), associated with fold structure (red) as channels that water outflowing from reservoir.



# Structure controlled; Fracture and Fold associated Fault


Discontinuities  
Avr. N27°W 63°SW



Poles

Type	Strike/Dip (Right)
Fault 1	169/69
Bedding	140/48
Fault 2	150/72

Equal Angle  
Lower Hemisphere  
100 Poles  
100 Entries



Stereo plot of discontinuities

Structural model of foundation




# 2-D Electrical survey lines

จุดตัดแนวสำรวจ		E*	N*	X	Y
A2	A6	509005.31	2112950.34	-50	150
A1	A6	509052.36	2112933.55	0	150
A3	A6	509099.50	2112916.73	50	150
A2	A7	508980.11	2112879.70	-50	75
A1	A7	509027.19	2112862.90	0	75
A3	A7	509074.33	2112846.09	50	75

Note \* พิกัด UTM Zone 47 Q


Chart Area



North

# Resistivity model

(looking NE)



South





Fig. 2. Model of water leakage by using electrical resistivity imaging data.

Note: Tunnel direction = N20°E, scale X:Y:Z = 1:1:1




# Area of seepage and leakage at surface






# Depth slices of resistivity anomaly at roof, middle and floor of tunnel from 6+285 to 6+495, area 210x160 m, slice interval of 2.5 m



# 162 tunnel faces ; km 6+249.5 – 6+500.5

Kob\_MainPC\_Works > Management\_งาน > 2564\_ห้วยแม่ประจักษ์\_เขื่อนใหม่ > แบบ และ face mapping > map ใต้ถ้ำแม่ประจักษ์

Search map ใต้ถ้ำแม่ประจักษ์



Lithology, Discontinuity, Leakage, Seepage, Volume of flow (L/min) : Cr.LSC1


# Interpreted arriving station of water flow-in along tunnel conduit, km 6+249.5 – 6+500.5, beneath reservoir

- 1) 6+269.5 – 6+352.5
- 2) 6+376.0 – 6+425.5
- 3) 6+458.5 – 6+500.5

6+249.5



6+450.5





# Combination

- Geological observation (surface)
  - Discontinuity analysis by stereo plot
  - Rock exposure study
- Geophysics (in between)
  - Resistivity profile
  - Resistivity modeling
  - Depth slides
- Tunnel faces analysis (sub-surface)



# Summary

- Geology, geophysics, and analysis of discontinuity system point out the model of water leakage
- Water leaks out from Huai Mae Prachum reservoir and flows down to tunnel conduit beneath
- Inflow from opened cracks at outcrops and reservoir floor, flows down through fracture zones, and arrives tunnel,
  - Station 6+248 – 6+500 km, (3 zones)
  - Elevation +372 – +377 m MSL.,
  - Direction of North 27° to West and dipping angle of 63° to South-west

# To the present day

- The treatment of tunnel has been preliminary conducted for awhile.
- Reservoir floor will be the next step to be treated
- Finish designing work
- Waiting for budget for reservoir improving and safety



# References

- Loke, M. H., 1999, Electrical imaging surveys for environmental and engineering studies: a practical guide to 2-D and 3-D surveys. Sunnyvale: Geometrics
- Royal Irrigation Department, 2005, Plan no. 109, Bidding 46/2548
- Royal Irrigation Department, Bureau of large scale water resources development 1 (LSC1), 2018, 162 lithology data recorded on tunnel faces.
- Royal Irrigation Department, 2021, geological and geophysical report, Huai Mae Prachum reservoir, Mae Taeng, Chiang Mai, technical report Code GOPH 01/2564, 87 p.
- Singdaeng, P., 2017, Geological condition and Tunnel Ground Behavior Along Mae Ngad – Mae Kuang Transfer Tunnel Project, Asian Institute Technology, Thailand.
- Srisuthum, C., and Kanrtapik, A., 2020, case study on leakage of water from Huai Mae Prachum reservoir, internal report.
- Yangmee, V., 2015, Seismic reflection survey along Mae Ngad-Mae Kuang tunnel, internal report
- <http://www.google.co.th/map>
- <https://www.researchgate.net/publication/338472345/figure/fig3/>

# Thanks very much Q & A

